

Technical Bulletin

NUMBER 31 SEPTEMBER 2009

Gyro compass errors

It is important to check the error of the ship's gyro compass

The UK Club's inspectors, as well as third party surveyors working on behalf of the Club, have reported that there is a lack of understanding of the importance of checking the error of the ship's gyro compass.

Compass errors should be taken regularly whilst on passage (at least once a watch) and the repeaters checked for alignment with the master compass prior to sailing. Bearings of celestial bodies should be taken and computed to determine the gyro error when out of sight of land and transit bearings can be taken when coasting or under pilotage.

Navigators should be aware that the error can alter due to the ship's speed and should familiarise themselves with any 'speed correctors' fitted to the compass. The compass error should also be checked following any large alteration of course.

It should also be noted that PSC inspectors also regard the compass error book as an important navigational record.

			C	OMPAS	SS OB	SERVA	TION	LOG(Gyro/Ma	gnetic)			
NO.	: 121										SHIP	S NAME :	NEW BARONE	SS
1	SUI	"S POSITIO	CAL. FOR GYRO ERROR				CAL. FOR DEVIATION						REMARK	CRISER
11:		LONG	GIED	TREE	GYRO EEROR	NETHOD	GYR0 COURSE	CIESE	198.	MAG. CORRE	ØBV.	COURSE COURSE		
074	15 218	N 112.04	e -	-	-	-	235	247	200	237	600	243.	clarby thy	8
11.3		N 10-26.0		-	-	-	18.7"	182	1.34	188.3	5.70	1940	Rain	2/0
1600	19-3	N 112-22		-	-	-	190"	190'	1.3°W	191.3	4.7W	196?	Roing / cien	1 %
94	3 18:48	UIIIE		-	-	-	185	187'	IN	186	60	192	OVENCARET	17
		NESTE		-	-	~	187°	187	1.3 00	188-3	5.70	194'	cloudy shy	30
		112 576		-	-	-	189'	189'	0.9 W	189.9	4.10	194°	Opercart	1
123		IN' SOE		76.5	0.5%	0	200	205	0,500.	200.5	4.50	.205	found yst	4
		112°2656		093.1	0.16	OR	205	205	110	2.06	SW	2110	But Rase	1
-		112-046	-	258.4	0.4°E	O A2	2.08	208.4	0.70	209.1	4.900	214"	Stor Ret	*
		111 475		-	-	-	210	205	BW	210	60	216.	chy	
A set	1575.01		113.	113.3	0.36	Da	205	205"	0.700	205.7	4.30	210°	Bent Ret	r
-	-	11 04.68	226"	226.4	0.48	DAZ	201°	201.4'	1	201.8	rea	1 207	· Sted By	4
-				226.9	0.98	1 45		-		-	JW	210	claby	
1	11'58N		-	-	-	-	205	205	OW	205.4	-	211'	Nousky	



UK P&I CLUB IS MANAGED BY **THOMAS** MILLER For further information please contact: Loss Prevention Department, Thomas Miller P&I Ltd Tel: +44 20 7204 2307. Fax +44 20 7283 6517 Email: lossprevention.ukclub@thomasmiller.com